

# ML Defect Integrated Solution Demonstration

2/21/2010

## Outline

1. Background Information
2. Zero printable ML defect demonstration
3. Summary



# Background Information


## □ Why ML defect mitigation is needed?

- Due to concerns on availability of defect-free EUVL ML blanks

## □ How is ML defect mitigation achieved?

- ML sorting for suitability of different mask layers (e.g., defect requirement for the dark filed contact layer will be different from that of poly layer)
- Using absorber pattern to cover ML defects via pattern global x- and y-shifting
- ML defect proximity repair after patterning


Examples of ML defect covered by absorber & mitigated via proximity absorber repair



# Background Information (cont'd)

## Example of Pattern Shifted Mask at Scanner

( $\Delta y$  shift only as an illustration)



1. Load/align the mask as usual (please note that only device data are shifted, reticle alignment mark/ PPF does not shift). Mask is centered on the stage
2. Input  $\Delta y$  shift in scanner to shift the reticle stage by  $-\Delta y$  such that device center matches to scanner optics center
3. Print wafer

# Background Information (cont'd)

## Zero Printable ML Defect Integrated Solution


**Solution: Combine low defect ML with absorber covering scheme**

**Goal: No printable ML defects on the finished EUVL mask**

- Zero printable ML defect in final mask is likely achievable if
  - ML blank has only a few printable defects
  - Mask has high/low pattern density
  
- ❑ It requires several key capabilities (long term solution)
  - ML with a few printable defects
  - Fiducial mark standardization
  - ML blanks with fiducial marks that meet SEMI-standard
  - High defect inspection tool stage precision and accuracy
  - Auto mask pattern shift software
  - EUV AIMS tool for proximity repair and final defect mitigation verification



# Demonstration Step 1: Select Lowest Defect Blank & Determine Preferred Orientation




- Blank has total of 8 defects  $\geq 70$  in  $132 \times 132 \text{mm}^2$  and 3 defects in the device area with preferred horizontal rotation.

# Step 2: Select another ML Blank and Create Fiducial/ML Defects to Mimic Blank A (to save blank A for actual mask fabrication)


Mark defects with locations identical to that of blank A

3 defects are within pattern field for indicated blank orientation



# Step 3: Deposit TaN and Pattern E-beam Alignment Marks


Def ID	X ( $\mu\text{m}$ )	Y ( $\mu\text{m}$ )
Def #1	23297.452	-27448.091
Def #2	33496.472	-18878.988
Def #3	-32152.748	31213.513




# Step 4: Determine Defect Location Correlation to E-beam Mark

1. We first measured locations via M1350, found ~800nm repeatability error .
2. Then measured known e-beam patterned locations, found  $>2\mu\text{m}$  accuracy error

M1350 defect location repeatability  
(3 measurements)



M1350 measurement vs. designed location (e-beam stage error neglected)




- Defect location measurement error in M1350 found are not acceptable.





# Re-measured Defect Locations Using a Mask Registration Tool

Position difference found between registration tool and M1350






- The registration tool measurement were assumed to be accurate and are used in the experiment.

# Step 5: Estimate Defect Size and Determine Required Absorber Pad Size

Optical image  $\sim 2\mu\text{m}$   
M7360 pixel 41

Optical Image  $\sim 0.5\mu\text{m}$   
M7360 pixel 22  
 $\text{SiO}_2$  equivalent:  $120\mu\text{m}$


Optical Image  $\sim 0.3\mu\text{m}$   
M7360 pixel 14  
 $\text{SiO}_2$  equivalent:  $75\text{nm}$



- Optical image seems to estimate larger defect size than that of M7360 calibrated  $\text{SiO}_2$  equivalent size
- Based on the optical image estimated defect size, we would need absorber pad sizes of  $2.5\text{-}3.0\mu\text{m}$ ,  $1.0\text{-}1.5\mu\text{m}$ , and  $\sim 1.0\mu\text{m}$  sizes for defect #1, #2, and #3, respectively, given possible alignment error + defect location measurement error.


# All 3 Defects are Found at Close Proximity of the Full Field Test Device Pattern

-field size (4x) ~90mmx120mm



- If no mitigation scheme applied, all defects are expected to be printable.

# Step 6: Pattern Shift Solution to Cover All 3 Defects was Found



- If defects are successfully covered, they are expected non-printable.

# Results:




## Pattern Shift Solution Verified in Final Mask

X-gap~3.7 $\mu$ m




Y-gap~2.5 $\mu$ m

X-gap=1.1 $\mu$ m

Designed defect location after pattern shift



Actual defect location after mask patterning



- All three defects are successfully covered as designed with negligible errors.
- All three defects at different sizes (as indicated by the red boxes) are successfully covered with additional margins.

# Conclusions

ML defect mitigation solution with full field pattern demonstrated

- All three defects are successfully covered by absorber with negligible error and extra margins.
  - Key successful factor is the defect location and fiducial mark location measurement accuracy
- Such complete coverage will lead to ML defect free printing.



# Acknowledgement

Guojing Zhang , Marilyn Kamna, Ken Buckmann, and Yan Liu

